





Schaubild

Flexible Brennerkörper



CORRECT

Flex *should be* distributed along torch neck to obtain *banana shape* profile.



INCORRECT

Do not flex torch neck abruptly 90° as this will break internal tubes.